

AD-A106 617

HOSKINS-WESTERN-SONDEREGGER INC LINCOLN NE

F/G 13/13

NATIONAL DAM SAFETY PROGRAM, LAKE HANNIBAL ESTATES UPPER DAM (M--ETC(U)


OCT 80 R S DECKER, G G JAMISON, G ULMER

DACW43-80-C-0071

NL

UNCLASSIFIED

[04]
AD A
10-441



AL A100617

LEVEL II

MISSISSIPPI-SALT-QUINCY BASIN

①

LAKE HANNIBAL ESTATES UPPER DAM

RALLS COUNTY, MO.

MO 11185

DTIC
ELECTE
OCT 01 1981
S D
E

**PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**



United States Army
Corps of Engineers
... Serving the Army
... Serving the Nation

St. Louis District

FILE COPY

PREPARED BY: U.S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

OCTOBER, 1980

This document has been approved
for public release and sale; its
distribution is unlimited.

81 10 29 051

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. <i>AD-A106617</i>	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Lake Hannibal Estates Upper Dam (MO 11185) Ralls County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Hoskins-Western-Sonderegger, Inc.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) DACW43-80-C-0071 ✓
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE October 1980
		13. NUMBER OF PAGES Approximately 70
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CLASSIFICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data bases, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.

Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.

Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

Block 10. Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")

Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.

Block 13. Number of Pages. Enter the total number of pages.

Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

Blocks 15 & 15a. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 17. Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .

Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

Block 20. Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.

LAKE HANNIBAL ESTATES UPPER DAM
RALLS COUNTY, MISSOURI
MISSOURI INVENTORY NO. MO 11185

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Lake Hannibal Estates Upper Dam (MO 11185),
Mississippi - Salt - Quincy Basin,
Ralls County, MO, Phase I Inspection Report.

PREPARED BY
HOSKINS-WESTERN-SONDEREGGER, INC.
CONSULTING ENGINEERS
LINCOLN, NEBRASKA

UNDER DIRECTION OF
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
FOR
GOVERNOR OF MISSOURI

OCT 1980

9, Final rept.,

15 / DACW43-80-C-0071
10 / Rey S. /Decker Gordon G. /Jamison
Garold /Ulmer Harold P. /Hoskins

Accession For	
NTIS GRI&I	X
DTIC TAB	
Unannounced	
Justification	
By	
Distribution/	
Availability Codes	
Dist Special	
A	



REPLY TO
ATTENTION OF

DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 TUCKER BOULEVARD, NORTH
ST. LOUIS, MISSOURI 63101

SUBJECT: Lake Hannibal Estates Upper Dam Phase I Inspection Report

This report represents the results of field inspection and evaluation of the Lake Hannibal Estates Upper Dam (MO 11185).

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- a. Spillway will not pass 50 percent of the Probable Maximum Flood without overtopping the dam.
- b. Overtopping of the dam could result in failure of the dam.
- c. Dam failure significantly increases the hazard to loss of life downstream.

SUBMITTED BY: SIGNED 5 JUN 1981
Chief, Engineering Division Date

APPROVED BY: SIGNED 8 JUN 1981
Colonel, CE, District Engineer Date

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

TABLE OF CONTENTS

<u>PARAGRAPH NO.</u>	<u>TITLE</u>	<u>PAGE NO.</u>
	Assessment Summary	
	Overview Photograph	
	SECTION 1 - PROJECT INFORMATION	
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	3
	SECTION 2 - ENGINEERING DATA	
2.1	Design	8
2.2	Construction	8
2.3	Operation	8
2.4	Evaluation	8
	SECTION 3 - VISUAL INSPECTION	
3.1	Findings	10
3.2	Evaluation	13
	SECTION 4 - OPERATIONAL PROCEDURES	
4.1	Procedures	14
4.2	Maintenance of Dam	14
4.3	Maintenance of Operating Facilities	14
4.4	Description of Any Warning System in Effect	14
4.5	Evaluation	14
	SECTION 5 - HYDRAULIC/HYDROLOGIC	
5.1	Evaluation of Features	15
	SECTION 6 - STRUCTURAL STABILITY	
6.1	Evaluation of Structural Stability	17
	SECTION 7 - ASSESSMENT/REMEDIAL MEASURES	
7.1	Dam Assessment	18
7.2	Remedial Measures	19

APPENDIX A - MAPS

Plate A-1	Vicinity Topography
Plate A-2	Location Map

APPENDIX B - PHOTOGRAPHS

		Photo Index
Plate B-1		
Plate B-2	Photo No. 2	Upstream Face From Left End
	Photo No. 3	Dam Crest From Left End
Plate B-3	Photo No. 4	Downstream Slope From Left End
	Photo No. 5	Principal Spillway Inlet From Crest
Plate B-4	Photo No. 6	Principal Spillway Inlet With Adjustable Hood
	Photo No. 7	Principal Spillway Outlet From Crest
Plate B-5	Photo No. 8	Downstream Slope From Right End
	Photo No. 9	Crest From Right End.
Plate B-6	Photo No. 10	Upstream Slope From Right End
	Photo No. 11	Erosion Area on Right Upstream Face
Plate B-7	Photo No. 12	Looking Upstream in Emergency Spillway Channel
	Photo No. 13	Looking Downstream in Emergency Spillway Channel
Plate B-8	Photo No. 14	Looking Downstream at Principal Spillway Outlet Pipe
	Photo No. 15	Looking From Left to Right at Principal Spillway Outlet Pipe
Plate B-9	Photo No. 16	Excavated Ditch at Left Side of Principal Spillway Outlet Pipe
	Photo No. 17	Cattail Area Around Emergency Lift Pump
Plate B-10	Photo No. 18	Downstream Hazards
	Photo No. 19	Downstream Hazards
Plate B-11	Photo No. 20	Downstream Hazard

APPENDIX C - PROJECT PLATES

Plate C-1	Phase I -	Plan of Dam
Plate C-2	Phase I -	Profile Along Centerline of Dam, Maximum Cross Section of Dam, Profile Along Centerline of Emergency Spillway
Plate C-3	SCS -	Plan and Design Data

APPENDIX D - HYDRAULIC AND HYDROLOGIC DATA

Plates D-1 and D-2	Hydrologic Computations
Plate D-3	Principal Spillway Rating Curve
Plate D-4	Emergency Spillway Rating Curve
Plate D-5	Ratio-Discharge Curves
Plate D-6	Elevation - Area Curve
Plates D-7 through D-26	Computer Input and Output for Ratios of PMF

PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM
ASSESSMENT SUMMARY

Name of Dam	Lake Hannibal Estates Upper Dam
State Located	Missouri
County Located	Ralls County
Stream	Big Creek
Date of Inspection	October 8, 1980

Lake Hannibal Estates Upper Dam was inspected by an interdisciplinary team of engineers from Hoskins-Western-Sonderegger, Inc. The purpose of the inspection was to make an assessment of the general conditions of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and developed with the help of several Federal and State agencies, professional engineering organizations, and private engineers.

Lake Hannibal Estates Upper Dam has a height of nineteen (19) feet and a storage capacity at the minimum top elevation of the dam of one hundred ninety-four (194) acre-feet. In accordance with the guidelines, a small size dam has a height greater than or equal to twenty-five (25) feet but less than forty (40) feet and a storage capacity greater than or equal to fifty (50) acre-feet but less than one thousand (1,000) acre-feet. The size classification is determined by either the storage capacity or height, whichever gives the larger size category. Lake Hannibal Estates Upper Dam is classified as a small size dam.

In accordance with the guidelines and based on visual observation, the dam is classified as having a high hazard potential. Failure would threaten life and property. The estimated damage zone extends approximately three (3) miles downstream of the dam. Within the damage zone are another dam (MO 10061) at three-tenths of a mile downstream; Highway H at four-tenths of a mile downstream; several camp trailers, a barn and a house located between the lower dam and Highway H; a trailer home and a house under construction at one-half mile downstream; a house at two and nine-tenths miles downstream, and a garage and trailer home at three miles downstream.

Our inspection and evaluation indicates that the spillways do not meet the criteria set forth in the recommended guidelines for a small dam having a high hazard potential. Considering the small volume of water impounded and the reservoir and dam (MO 10061) immediately downstream, one half of the Probable Maximum Flood is the appropriate spillway design

flood. The hydraulic/hydrologic analyses based on the adjustable "goose-neck" type inlet being set at invert elevation of 97.0 indicate that the spillways will not pass the 100-year flood (1% probability flood - a flood having a one percent chance of being exceeded in any one year) without overtopping the dam. The spillway will pass 14% of the Probable Maximum Flood and the 10-year flood (a flood having a ten percent chance of being exceeded in any one year) without overtopping the dam. The Probable Maximum Flood is defined as the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonable possible in the region.

Rotation of the "gooseneck" type inlet to its highest invert elevation of 99.0 would result in the spillways not being able to pass the 10-year flood without overtopping the dam. Failure of the spillways to pass the 10-year flood would change the classification of the dam from Unsafe-Non-emergency to Unsafe-Emergency.

This dam appears to be in excellent structural condition. The deficiencies noted are inadequate spillway capacity, the lack of seepage and stability analyses as required by the guidelines for all dams having a high hazard potential, some erosion of the upstream slope and an open excavation along the left side of the principal spillway conduit. The adjustable "gooseneck" type inlet is also considered a deficiency since rotation of the invert upwards increases the possibility of overtopping of the dam.

Minimal design data were available for this dam. Based on the data available and on the observations made during the field inspection of the dam, the following remedial measures should be performed under the guidance of a professional engineer experienced in the design and construction of dams:


a. Alternatives.

- (1) The emergency spillway size and/or the height of dam should be increased to pass 50% of the Probable Maximum Flood without overtopping. In either case the spillway should be protected to prevent erosion.

b. Operation and Maintenance Procedures.

- (1) Seepage and stability analyses comparable to the requirements of the recommended guidelines should be performed by an engineer experienced in the design and construction of dams.
- (2) Measures should be taken to repair present erosion and to stabilize the upstream slope.


- (3) The excavation to uncover the valve on the 2-inch outlet pipe should be filled and stabilized. The outlet pipe should be maintained and operated periodically.
- (4) Measures should be taken to assure that the elevation of the invert of the principal spillway inlet does not exceed 97.0.
- (5) Maintenance of the vegetation on the embankment and emergency spillway is excellent and should be continued.
- (6) A trash rack should be installed on the principal spillway inlet to help in keeping the spillway open.
- (7) Periodic inspections of the dam should be made and recorded as part of this project file.




Rey S. Decker
E-3703



Gordon Jamison



Garold Ulmer
E-19246



Harold P. Hoskins, Chairman of the Board
Hoskins-Western-Sonderegger, Inc.
E-8696



PHOTO NO. 1 - OVERVIEW

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
LAKE HANNIBAL ESTATES UPPER DAM - MO - 11185
RALLS COUNTY, MISSOURI

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

- a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of Lake Hannibal Estates Upper Dam be made.
- b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.
- c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams", Appendix D to "Report of the Chief of Engineers on the National Program of Inspection of Dams", dated May, 1975, and published by the Department of the Army, Office of the Chief of Engineers.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances.
 - (1) Embankment. The dam is an earth fill structure approximately 600 feet in length and 19 feet in height with a maximum storage capacity at the minimum top elevation of dam of 194 acre-feet. The dam impounds recreational water for a housing development. Immediately downstream (approximately 1500 feet) is another dam (MO 10061). The impounded water in the lower reservoir encroaches upon the downstream toe of this dam. Both dams are owned by the same developer.
 - (2) Principal Spillway. The principal spillway was designed by SCS as a hood inlet type spillway with no control feature. During construction the hood was replaced with a "gooseneck" type corrugated metal pipe inlet which can be rotated in order to adjust the level of the water in the reservoir.

- (a) Inlet Structure. The "gooseneck" type inlet is constructed of 24-inch diameter corrugated metal pipe and is attached to the inlet end of the conduit by a 24-inch length corrugated metal pipe band with manually tightened bolts. The effective invert elevation of the inlet can be raised by loosening the bolts and rotating the inlet. The "gooseneck" type inlet is shown in Photo No. 6.
- (b) Conduit. The principal spillway conduit is 24-inch corrugated metal pipe having a length of 135 feet. The inlet invert elevation for the conduit is 97.0, and the outlet invert is at elevation 83.6. The SCS plan shows that the conduit is equipped with two anti-seep collars.
- (c) Stilling Basin. The upper end of the lower reservoir (MO 10061) serves as a stilling basin.
- (3) Emergency Spillway. The uncontrolled vegetated earth emergency spillway is cut through the right abutment. The bottom width is approximately 60 feet, and the side slopes vary. A road across the entrance channel serves as an outlet control. There is a training dike on the left side of the exit channel. The emergency spillway profile is shown on Plate C-2.
- (4) Low-Level Outlet. The only low-level outlet is a 2-inch pipe through the dam with a valve at the downstream end.
- (5) Pertinent physical data are given in paragraph 1.3.
- b. Location. The dam is located within the corporate limits of Rensselaer in the north central part of Ralls County, Missouri, as shown on Plate A-2. The dam is shown on Plate A-1 in the NW 1/4 of Section 11, T56N, R6W.
- c. Size Classification. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. This dam has a height of 19 feet, a storage capacity of 194 acre-feet and is classified as a small size dam. A small size dam has a height greater than or equal to 25 feet but less than 40 feet and a storage capacity greater than or equal to 50 acre-feet but less than 1,000 acre-feet. The size classification is determined by either the storage or height, whichever gives the larger size category.
- d. Hazard Classification. Guidelines for determining hazard classification of dams and impoundments are presented in the guidelines as referenced in paragraph 1.1c above.

Aerial photographs of the downstream damage zone of this dam were taken in October, 1980. These photographs were used as reference in the field observations of the damage zone which were made during the inspection. Based on the field observations and on the referenced guidelines this dam is in the High Hazard Potential Classification. The estimated damage zone extends approximately three miles downstream of the dam. Within the damage zone are another dam (MO 10061) at three-tenths of a mile downstream; Highway H at four-tenths of a mile downstream; several camp trailers, a barn and a house located between the lower dam and Highway H; a trailer home and a house under construction at one-half mile downstream; a house at two and nine-tenths miles downstream, and a garage and trailer home at three miles downstream.

- e. Ownership. The dam is owned by Lake Hannibal Estates, P.O. Box 430, Hannibal, Missouri 63401, c/o Tom Hulse.
- f. Purpose of Dam. The dam was constructed to impound water for recreational purposes.
- g. Design and Construction History. Rudimentary design assistance was provided by the Soil Conservation Service, New London, Missouri. One plan sheet prepared by SCS is included within this report as Plate C-3 in Appendix C. The dam was constructed in 1968.
- h. Normal Operating Procedure. The pool level is controlled by rainfall, infiltration, evaporation, and the capacity of the uncontrolled spillways. The volume of water impounded can be increased by rotation of the "gooseneck" type inlet upward so that the invert elevation of the inlet is higher than the invert elevation of the conduit to which it is connected.

1.3 PERTINENT DATA

- a. Drainage Area. 306 acres (0.478 square miles), from SCS Plans.
- b. Discharge at Damsite.
 - (1) All discharges at the damsite are through the following:
 - (a) A 24-inch diameter principal spillway consisting of a corrugated metal pipe conduit equipped with a "gooseneck" type corrugated metal pipe inlet. The inlet can be manually rotated in order to impound water above the invert elevation of the conduit to which the inlet is connected. The spillway is uncontrolled after the invert elevation of the inlet has been set.

(b) An uncontrolled, vegetated earth channel emergency spillway.

- (2) Estimated maximum flood at damsite -- unknown.
- (3) The principal spillway capacity varies from 0 c.f.s. at elevation 97.0 feet to 14 c.f.s. at the crest of the emergency spillway (elevation 99.2 feet) to 36 c.f.s. at the minimum top of dam (elevation 100.2 feet).
- (4) The emergency spillway capacity varies from 0 c.f.s. at its crest (elevation 99.2 feet) to 100 c.f.s. at the minimum top of dam (elevation 100.2 feet).
- (5) Total spillway capacity at the minimum top of dam is 136 c.f.s. \pm .

c. Elevations (feet - SCS Plans).

- (1) Observed pool - 96.0
- (2) Normal pool - 97.0
- (3) Spillway crests
 - Principal - 97.0
 - Emergency - 99.2
- (4) Maximum experienced pool - 99.7 \pm (based on statement by Mr. Hulse that the spillway operated in 1973 with flow depth of 6 inches.)
- (5) Top of dam (minimum) - 100.2
- (6) Streambed - 81.5
- (7) Maximum Tailwater - unknown

d. Reservoir. Length (feet) of pool

- (1) At principal spillway crest - 2100 \pm
- (2) At emergency spillway crest - 2350 \pm
- (3) At top of dam (minimum) - 2450 \pm

e. Storage (Acre-feet).

- (1) Observed pool - 95±
- (2) Normal pool - 115±
- (3) Spillway crests
 - Principal - 115±
 - Emergency - 165±
- (4) Maximum experienced pool - 180±
- (5) Top of dam (minimum) - 194±

f. Reservoir Surface (Acres).

- (1) Observed pool - 18±
- (2) Normal pool - 20±
- (3) Spillway crests
 - Principal - 20±
 - Emergency - 26±
- (4) Maximum experienced pool - 28±
- (5) Top of dam (minimum) - 31±

g. Dam.

- (1) Type - Earth fill
- (2) Length - 600 feet (plans & measured)
- (3) Height - 19± feet
- (4) Top Width - 14± feet
- (5) Side slopes.
 - (a) Downstream - 1V on 5H (measured)
 - (b) Upstream - 1V on 5H (measured to water level)
- (6) Zoning - Homogeneous

- (7) Impervious core - Homogeneous
- (8) Cutoff - Plans show 3 feet minimum depth, 10 feet bottom width and 1V on 1H side slopes. Mr. Hulse reported that the cutoff extended to about 10 feet in depth and was bottomed in clay.
- (9) Grout curtain - None
- (10) Wave protection - Vegetated earth
- (11) Drains - None
- h. Diversion Channel and Regulating Tunnel. None
- i. Spillways.
 - (1) Principal
 - (a) Type. A 24-inch corrugated metal pipe conduit equipped with a "gooseneck" type corrugated metal pipe inlet. The invert elevation of the inlet can be adjusted by rotating the inlet.
 - (b) Crest (invert) elevation - 97.0 (Conduit invert elevation at juncture with inlet. Maximum rotation of inlet would result in an inlet invert elevation of 99.0±. 97.0 is used in the hydraulic/hydrologic analysis of this dam).
 - Outlet (invert)elevation - 83.6
 - (c) Length - 135 feet
 - (2) Emergency
 - (a) Type - An uncontrolled vegetated earth spillway excavated through the right abutment. Bottom width - approximately 60 feet. Side slopes vary. See Plate C-2 for inlet and exit slopes.
 - (b) Control section - Graveled road approximately 10-feet in width following the centerline of dam.
 - (c) Crest elevation - 99.2

(d) Upstream Channel - Open and clear - vegetated.

(e) Downstream Channel - Open and clear - vegetated.
Discharges directly into lower
reservoir approximately 400 feet
downstream from centerline of
this dam.

j. Regulating Outlets. None

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

Rudimentary design assistance was provided by the Soil Conservation Service, New London, Missouri. One plan sheet prepared by SCS was obtained from the New London office and is included within this report as Plate C-3 in Appendix C. Differences between data shown on the plan sheet and actual construction are referred to throughout this report as well as on the typewritten insert which has been added in the preparation of Plate C-3.

2.2 CONSTRUCTION

No construction data were available. Mr. Hulse reported that the dam was constructed in 1968. He also reported that the embankment slopes were constructed flatter than shown on the plans and that the cutoff trench was about 10 feet in depth and bottomed in clay.

2.3 OPERATION

- a. A 2-inch steel pipe passes through the dam along the principal spillway conduit. A control valve is located near the downstream toe of the dam. Flow from this pipe can be directed into the lower lake or into a pumping station located downstream from the left end of the dam for fire protection and other water uses. Mr. Hulse reported that the pump station was no longer needed or used since the water system had been completed for the development and that the pump station was to be removed.
- b. The "gooseneck" type principal spillway inlet is an operating feature of this dam since it can be rotated in order to adjust the spillway invert elevation. At the date of inspection the invert elevation of the "gooseneck" inlet was lower than the invert elevation of the spillway conduit to which it is connected. Maximum rotation of the inlet upwards could raise the level of the water in the reservoir to the approximate level of the control section of the emergency spillway.

2.4 EVALUATION

- a. Availability. All available data were readily provided by the Soil Conservation Service.
- b. Adequacy. The field surveys, visual observations and plans presented herein are considered adequate to support the conclusions of this report. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a

deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

- c. Validity. Data that were available are considered to be valid, as modified during construction.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

- a. General. A visual inspection of the Lake Hannibal Estates Dam was made on October 8, 1980. Engineers from Hoskins-Western-Sonderegger, Inc., Lincoln, Nebraska, making the inspection were:

Rey S. Decker - Geotechnical
Garold G. Ulmer - Hydraulics and Hydrology
Gordon Jamison - Hydraulics and Hydrology

The owner was represented during the inspection by Mr. Tom Hulse.

- b. Geology and Soils (abutment and embankment). This site is situated in the loess-till central Mississippi physiographic area. Upland soils in the area consist of the Menfro and Winfield series developed on loess and the Lindley developed on glacial till on the lower slopes. These loess and till materials mantle the Mississippian age Kinderhookian series of the Hannibal formation and the Chauteau group. These bedrock formations consist of fissile siltstones, shales, and undifferentiated limestone and dolomite.

The only significant structural feature in the area is the NW-SE trending Lincoln Fold, the axis of which is about one mile west of the site. No significant faulting has been recognized in the area.

The site is located in Seismic Zone 1 with minor probability of earthquake damage. The only reported earthquake within 25 miles is the August 8, 1930 quake of IV Modified Mercalli intensity.

Materials in the embankment and the abutments were sampled by hand auger and were field classified as CL loessial soils. Neither glacial till nor bedrock are exposed at this site. Limestone float rocks were observed on the lower slopes of the right (south) abutment of the lower dam (MO 10061) some 1500 feet downstream from this dam.

Catastrophic collapse due to solution cavitation in underlying carbonate bedrock is not reported in this vicinity. No evidence for this hazard was observed at the site or in the valley. Low yields in local wells are evidence of the low transmissivity and secondary porosity in the limestones and dolomites.

c. Dam.

- (1) Upstream Slope. The upstream slope is well vegetated. No cracks or deformations were observed. Some erosional damage was observed on the slope extending 2 or 3 feet vertically above present lake level. Some of the eroded areas had been stabilized with small size riprap. One active erosional area was observed between stations 5+00 and 5+25. This area has cut into the face about 8 feet horizontally and has a vertical scarp about 2 feet deep. Mr. Hulse reported that he places riprap whenever the erosion becomes significant and that he plans to repair this area in the near future. The slope of the upstream embankment, as determined during the inspection, is 1V on 5H as compared to 1V on 3H as shown on Plate C-8. There was no evidence to indicate that an upstream berm was constructed. Photos 2 and 10 show the upstream face, and Photo No. 11 shows the active erosional area.
- (2) Crest. The crest is well graveled and serves as an access road for the development. No cracks or serious erosion were observed on the crest. The profile of the crest, shown on Plate C-2, Appendix C, shows a distinct hump in the crest with top elevation of 102.2 for a distance of 50 feet± either side of the principal spillway (comparable to settled elevation of 102 shown on Plate C-3). The remainder of the dam is below the settled top elevation shown on Plate C-3 with a low elevation of 100.3 at the extreme left (stations 0+00 to 0+50) and 100.2 at station 6+00 on the extreme right at the left edge of the emergency spillway. There was no evidence that would indicate that the dam has been overtopped. Photos 3, 8 and 9 show the crest.
- (3) Downstream Slope. The downstream slope is very well vegetated with adapted grasses and is well mowed and maintained. No cracks, erosion, bulges, slides, deformations, tree growth or rodent activity were observed. No evidence of seepage was observed on the slope, in the abutment troughs or along the toe. The slope of the downstream embankment, as determined during the inspection, is 1V on 5H as compared to 1V on 4H as shown on Plate C-3. Photos 3, 4 and 8 show the downstream slope.

A wet spot with standing water was observed outside of the toe downstream from about station 2+50. Mr. Hulse reported that this is the pump station that is no longer used. It consists of a 1000-gallon tank equipped with a float valve system connected with the 2-inch pipe near the outlet of the principal spillway. Apparently the float valves are not operating effectively thus allowing the tank to overfill.

This water around the lift station does not appear to have any connection with seepage through the abutment. Mr. Hulse said that he plans to disconnect the inflow pipe at the valve near the principal spillway and to remove the storage tank and lift pump. Photo No. 17 shows the wet spot and the top of the storage tank. Photo No. 15 shows an excavated area just left of the spillway pipe where Mr. Hulse had uncovered the valve on the 2-inch pipe from the lake that supplies water to the lift station. Mr. Hulse plans to provide access for the valve and to refill this area.

d. Appurtenant Structures.

(1) Principal Spillway.

- (a) Inlet Structure. The 24-inch corrugated metal pipe spillway was designed with a conventional uncontrolled hooded inlet (Plate C-3). A manually controlled "gooseneck" type inlet was added to the inlet end of the spillway in lieu of the hood inlet. This inlet can be manually rotated to provide control over the elevation of the normal pool. The inlet was open and free, and no deterioration of the metal structure was apparent. Photos 5 and 6 show the inlet of the principal spillway.
 - (b) Conduit. The conduit consists of about 135 feet of 24-inch diameter corrugated metal pipe. No deterioration of the metal was observed at the inlet or outlet ends of the pipe. Mr. Hulse reported that the pipe was double-dipped and coated. Photos 7, 14 and 15 show the outlet of the conduit.
 - (c) Stilling Basin. The principal spillway discharges directly into the lower reservoir as shown in Photos 7 and 15.
- (2) Emergency Spillway. The emergency spillway is cut through the right abutment as opposed to the left abutment as shown on Plate C-3. The entire channel is well vegetated with adapted grasses. A retaining dike along the left side of the spillway exit channel diverts flows away from the embankment. The spillway discharges into the lower reservoir. Mr. Hulse reported that the emergency spillway operated in 1973 with a flow depth of about 6 inches. The graveled access road passes across the spillway and serves as the control section. Photos No. 12 and 13 show the emergency spillway.

- (3) Low-Level Outlet. The only low-level outlet consists of a 2-inch steel pipe through the dam located along the left side of the principal spillway. This outlet is controlled by a valve at the downstream end. Discharge from this pipe can be directed into the lower reservoir or into the pump station previously described. Photo No. 16 shows the excavation over the valve on this outlet pipe.
- e. Reservoir Area. The shore line of the reservoir is well vegetated with grass. No significant erosion was noted around the reservoir. There was no evidence of abnormal siltation in the reservoir. Photo No. 5 shows a portion of the reservoir area.
- f. Downstream Channel. The discharges from this reservoir flow directly into the lower reservoir (MO 10061).

3.2 EVALUATION

This structure appears to be in excellent structural condition with no apparent potential of failure. No seepage through the dam or abutments was observed, and the abnormally flat slopes should provide adequate safety against shear failures in a dam of this height and composition. A few minor deficiencies in maintenance (erosion of the upstream face and open excavation along the left side of the principal spillway outlet) could ultimately impair the safety of the structure and should be corrected.

The source of water around the lift station downstream from station 2+50 is reported as leakage from the storage tank. This reported source should be verified and eliminated by repairing or removing the system.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

The pool level is generally controlled by rainfall, infiltration, evaporation, and the capacity of the uncontrolled spillways. The only controlled outlet consists of a 2-inch steel pipe (with valve) through the embankment.

The "gooseneck" type inlet on the principal spillway presently keeps the normal pool level at the planned elevation of 97.0; however, it could be rotated upward to raise the normal pool elevation to a maximum elevation of 99.0±.

4.2 MAINTENANCE OF DAM

The dam is mowed regularly and is neat and clean in appearance. Maintenance of the upstream slope is reportedly done as needed. One eroded spot (station 5+00 - 5+25) needs to be repaired in the near future.

4.3 MAINTENANCE OF OPERATING FACILITIES

The 2-inch outlet system is operable but has not been used for a few years.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no warning system in effect for this dam.

4.5 EVALUATION

Maintenance of this structure is generally good. Prevention and/or repair of erosion on the upstream slope should be done on a regular basis rather than waiting until it becomes serious.

The "gooseneck" type inlet on the principal spillway should be removed or rivetted in place to prevent raising the normal pool level above elevation 97.0.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

- a. Design Data. One plan sheet containing design data was obtained from the New London, Missouri SCS office and is included as Plate C-3 in Appendix C of this report.
- b. Experience Data. The drainage area, reservoir surface area, and elevation-storage data were developed from the USGS Rensselaer, Missouri 7-1/2-minute topographic quadrangle map. The hydraulic computations for the spillway and dam overtopping discharge ratings were based on data collected in the field at the time of the field inspection. Hydrologic computations are attached as Appendix D of this report.
- c. Visual Observations.
 - (1) The principal spillway conduit appears to be in excellent condition. No deterioration of the corrugated metal pipe was observed at either inlet or outlet end. The "gooseneck" type inlet which can be adjusted by rotation upward to increase the level of the water impounded behind the dam is a cause of concern for reasons as stated in paragraph 5.1d. below.
 - (2) The emergency spillway is well vegetated on both sides of the graveled road control section as shown in Photos 12 and 13. A retaining dike along the left side of the exit channel will divert flows away from the downstream toe of the dam. The downstream channel is unobstructed and is well maintained.
 - (3) Erosion damage on the upstream slope should be repaired and measures taken to stabilize the slope.
 - (4) The presence of bends in the principal spillway inlet and the absence of a trash rack may result in the blockage of the spillway by debris resulting in a reduced spillway capacity.
- d. Overtopping Potential. The spillways are too small to pass 50% of the probable maximum flood without overtopping the dam. The spillways will pass 14% of the probable maximum flood and the 10% probability flood without overtopping. The spillways will not pass the 1% probability flood without minor overtopping (less than .3 foot for two hours). The hydraulic/hydrologic analyses of this dam is based on an invert elevation of 97.0 for the principal spillway (elevation of the principal spillway conduit at connection to the "gooseneck" type inlet). Rotation of the inlet upwards, resulting in the inlet invert elevation

being higher than the conduit invert elevation, will result in an increase in the volume of water impounded behind the dam and also a decrease in the amount of storm runoff that can be stored prior to flow occurring through the emergency spillway. The possibility of overtopping at both ends of the dam is enhanced by raising the elevation of the invert of the inlet. With the "gooseneck" type inlet raised to the highest position (invert at 99.0 ft) the spillway capacity would be lowered to 104 cfs, the spillways would pass 7% of the PMF, and the spillways would not pass the 10% probability flood without overtopping the dam. Overtopping of a dam should always be avoided. Overtopping would be dangerous because the flow of the water over the crest could erode the downstream face of the dam and, if continued long enough, could breach the dam with sudden release of all of the impounded water onto the downstream floodplain. It is recommended that the "gooseneck" type inlet be replaced with a hood inlet or that it be rivetted in place with its invert at elevation 97.0 or lower.

The results of the routings through the dam are tabulated in regards to the following conditions:

Frequency	Inflow Discharge c.f.s.	Outflow Discharge c.f.s.	Maximum Pool Elevation	*Maximum Depth Over Dam Feet	Duration Over Top Hours
1%	1260	230	100.5	0.3	2
1/2 PMF	2090	1800	101.5	1.3	6
PMF	4180	3840	102.1	1.9	9
0.14 PMF	600	136	100.2	0	-

*Minimum top of dam elevation - 100.2 feet.

According to the recommended guidelines from the Department of the Army, Office of the Chief of Engineers, this dam is classified as having a high hazard potential and a small size. Therefore, the 1/2 PMF to PMF is the test for the adequacy of the dam and its spillway.

The estimated damage zone is described in Paragraph 1.2d in this report.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observation. Based on visual inspection this dam appears to be structurally stable. There is no evidence of slips, slides, cracking, seepage, rodent borrows or deformations. The abnormally flat slopes should provide adequate safety against shear failures.
- b. Design and Construction Data. Design data as shown on Plate C-3 were available for this dam. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.
- c. Operating Records. The small operating facility for this dam has not been used for several years.
- d. Post Construction Changes. The inspection team is not aware of any post-construction changes. The embankment slopes were flattened, and the inlet to the principal spillway was modified during construction.
- e. Seismic Stability. This dam is located in Seismic Zone 1. An earthquake of the magnitude predicted in this area is not expected to cause structural failure of this dam.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

- a. Safety. Based on visual inspection, this dam appears to be in excellent structural condition, and maintenance is generally good. There were no cracks, bulges, slides or abnormal deformations that would indicate structural stress. The dam is free of tree and brush, and no rodent activity was observed. There was no seepage along the toe of the dam or in either abutment trough. The crest is used as a road and is well graveled. The downstream slope and the emergency spillway are well vegetated, and there was no evidence of erosion in either. The upstream slope is also well vegetated. Some erosional damage was observed on the upstream slope which, if not repaired, could ultimately impair the safety of the dam. An open excavation along the left side of the outlet end of the principal spillway conduit should be repaired.

The water standing in the wet spot near the pump station downstream from the toe of the dam is apparently overflow water from the tank at the pump station. The pump station is no longer used and will be removed.

The approximate hydraulic/hydrologic analyses performed for this dam were based on the invert elevation of the adjustable "gooseneck" type inlet being set at the elevation of the principal spillway conduit at the point of connection with the inlet section (97.0). These analyses indicate that minor overtopping (0.3 foot for a period of 2 hours) could be expected for the 1% probability flood. 50% of the probable maximum flood would overtop the dam by 1.3 feet for a period of 6 hours. In accordance with the "Recommended Guidelines for Safety Inspection of Dams" the capacity of the spillways is inadequate for a small dam having a high hazard potential rating. Rotation of the "gooseneck" type inlet to its highest invert elevation (99.0) would result in the spillways not being able to pass the 10% probability flood without overtopping the dam. It is recommended that the "gooseneck" type inlet be replaced with a hood inlet or that it be rivetted in place with its invert at elevation 97.0 or lower.

The failure of this dam by overtopping could suddenly release the impounded water into the downstream reservoir placing an almost unbearable stress on the simultaneously heavily stressed downstream dam (MO 10061) and resulting in possible failure of that dam. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

- b. Adequacy of Information. The design data furnished by the SCS and included as Plate C-3 of this report and the measurements and observations made during the inspection are considered adequate to support the conclusions and recommendations presented in this report. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.
- c. Urgency. There does not appear to be an immediate urgency to accomplish the remedial measures recommended in paragraph 7.2.b. The item recommended in paragraph 7.2.a. should be pursued on a high priority basis.
- d. Necessity for Further Investigations. Further investigations are not required.
- e. Seismic Stability. This dam is located in Seismic Zone 1. An earthquake of this magnitude is not expected to be hazardous to this dam. It is recommended, however, that the prescribed seismic loading for Seismic Zone 1 be applied in any stability analyses performed for this dam.

7.2 REMEDIAL MEASURES

The following remedial measures and maintenance procedures are recommended. All remedial measures should be performed under the guidance of a registered professional engineer experienced in the design and construction of earth dams.

a. Alternatives.


- (1) The emergency spillway size and/or the height of dam should be increased to pass 50% of the Probable Maximum Flood without overtopping. In either case, the spillway should be protected to prevent erosion.

b. Operation and Maintenance Procedures.

- (1) Seepage and stability analyses comparable to the requirements of the recommended guidelines should be performed by an engineer experienced in the design and construction of dams.
- (2) Measures should be taken to repair present erosion and to stabilize the upstream slope.
- (3) The excavation to uncover the valve on the 2-inch outlet pipe should be filled and stabilized. The outlet pipe should be maintained and operated periodically.

- (4) Measures should be taken to assure that the elevation of the invert of the principal spillway inlet does not exceed 97.0.
- (5) Maintenance of the vegetation on the embankment and emergency spillway is excellent and should be continued.
- (6) A trash rack should be installed on the principal spillway inlet to help in keeping the spillway open.
- (7) Periodic inspections of the dam should be made and recorded as part of this project file.

APPENDIX A
MAPS



Scale in feet
2000 1000 0 2000 4000

Contour Interval - 10'





VICINITY TOPOGRAPHY


LAKE HANNIBAL ESTATES UPPER DAM
RALLS COUNTY, MO.

MO 11185

PLATE A-1



VICINITY MAP
MO 11185
RALLS COUNTY, MISSOURI



LOCATION MAP
PLATE A-2

APPENDIX B
PHOTOGRAPHS



LAKE HANNIBAL ESTATES UPPER DAM

RALLS COUNTY, MO.

MO 11185

PHOTO INDEX

PLATE B-1



PHOTO NO. 2 - UPSTREAM FACE FROM LEFT END.




PHOTO NO. 3 - DAM CREST FROM LEFT END.



PHOTO NO. 4 - DOWNSTREAM SLOPE FROM LEFT END.



PHOTO NO. 5 - PRINCIPAL SPILLWAY INLET FROM CREST.



PHOTO NO. 6 - PRINCIPAL SPILLWAY INLET WITH ADJUSTABLE HOOD.



PHOTO NO. 7 - PRINCIPAL SPILLWAY OUTLET FROM CREST.



PHOTO NO. 8 - DOWNSTREAM SLOPE FROM RIGHT END.



PHOTO NO. 9 - CREST FROM RIGHT END.



PHOTO NO. 10 - UPSTREAM SLOPE FROM RIGHT END.



PHOTO NO. 11 - EROSION AREA ON RIGHT UPSTREAM FACE.



PHOTO NO. 12 - LOOKING UPSTREAM IN EMERGENCY SPILLWAY
CHANNEL.



PHOTO NO. 13 - LOOKING DOWNSTREAM IN EMERGENCY SPILLWAY
CHANNEL.



PHOTO NO. - 14 LOOKING
DOWNSTREAM AT PRINCIPAL
SPILLWAY OUTLET PIPE.




PHOTO NO. 15 - LOOKING FROM LEFT TO RIGHT AT PRINCIPAL
SPILLWAY OUTLET PIPE.



PHOTO NO. 16 - EXCAVATED DITCH AT LEFT SIDE OF PRINCIPAL
SPILLWAY OUTLET PIPE.



PHOTO NO. 17 - CATTAIL AREA AROUND EMERGENCY LIFT PUMP.



PHOTO NO. 18 - DOWNSTREAM HAZARDS. CAMPING TRAILERS IN
PARK JUST DOWNSTREAM FROM LOWER RESERVOIR.




PHOTO NO. 19 - DOWNSTREAM HAZARDS. TRAILER HOME, SMALL
HOUSE, AND NEW CONSTRUCTION ON RIGHT BANK
APPROXIMATELY 1/4 MILE BELOW LOWER RESERVOIR.



PHOTO NO. 20 - DOWNSTREAM HAZARD. HOME ON HIGH LEFT BANK
APPROXIMATELY TWO MILES DOWNSTREAM. PROBABLY
NOT IN DANGER.

APPENDIX C
PROJECT PLATES




LAKE HANNIBAL ESTATES UPPER DAM

RALLS, COUNTY, MO.


MO 11185

PLAN OF DAM


PLATE C-1




PROFILE ALONG CENTERLINE OF DAM



MAXIMUM CROSS-SECTION OF DAM AT STA. 3+95




PROFILE ALONG CENTERLINE OF EMERGENCY SPILLWAY



PHASE I INSPECTION:

- 11) Hood Inlet replaced with "gooseneck" type adjustable inlet during construction.
- 12) Watershed Map shows dam in Sec. 10 instead of Sec. 11.
- 13) Spillway modified to accommodate vehicular traffic.
- 14) Spillway shown on left side on plan. Constructed on right side.
- 15) Upstream and downstream slopes are 1V on 5H instead of as shown above.



DESIGN DATA

INCREASED WATER 306
 2 W. 10 8 W. 17 10 14 15 51 9 48
 3 10 15 20 25 30 35 40 45 50 55 60 65 70 75 80 85 90 95 100
 100 110 120 130 140 150 160 170 180 190 200 210 220 230 240 250 260 270 280 290 300
 310 320 330 340 350 360 370 380 390 400 410 420 430 440 450 460 470 480 490 500
 510 520 530 540 550 560 570 580 590 600 610 620 630 640 650 660 670 680 690 700 710
 720 730 740 750 760 770 780 790 800 810 820 830 840 850 860 870 880 890 900 910
 920 930 940 950 960 970 980 990 1000 1010 1020 1030 1040 1050 1060 1070 1080 1090 1100 1110 1120
 1130 1140 1150 1160 1170 1180 1190 1200 1210 1220 1230 1240 1250 1260 1270 1280 1290 1300 1310 1320 1330
 1340 1350 1360 1370 1380 1390 1400 1410 1420 1430 1440 1450 1460 1470 1480 1490 1500 1510 1520 1530 1540
 1550 1560 1570 1580 1590 1600 1610 1620 1630 1640 1650 1660 1670 1680 1690 1700 1710 1720 1730 1740
 1750 1760 1770 1780 1790 1800 1810 1820 1830 1840 1850 1860 1870 1880 1890 1900 1910 1920 1930 1940
 1950 1960 1970 1980 1990 2000 2010 2020 2030 2040 2050 2060 2070 2080 2090 2100 2110 2120 2130 2140
 2150 2160 2170 2180 2190 2200 2210 2220 2230 2240 2250 2260 2270 2280 2290 2300 2310 2320 2330 2340
 2350 2360 2370 2380 2390 2400 2410 2420 2430 2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540
 2550 2560 2570 2580 2590 2600 2610 2620 2630 2640 2650 2660 2670 2680 2690 2700 2710 2720 2730 2740
 2750 2760 2770 2780 2790 2800 2810 2820 2830 2840 2850 2860 2870 2880 2890 2900 2910 2920 2930 2940
 2950 2960 2970 2980 2990 3000 3010 3020 3030 3040 3050 3060 3070 3080 3090 3100 3110 3120 3130 3140
 3150 3160 3170 3180 3190 3200 3210 3220 3230 3240 3250 3260 3270 3280 3290 3300 3310 3320 3330 3340
 3350 3360 3370 3380 3390 3400 3410 3420 3430 3440 3450 3460 3470 3480 3490 3500 3510 3520 3530 3540
 3550 3560 3570 3580 3590 3600 3610 3620 3630 3640 3650 3660 3670 3680 3690 3700 3710 3720 3730 3740
 3750 3760 3770 3780 3790 3800 3810 3820 3830 3840 3850 3860 3870 3880 3890 3900 3910 3920 3930 3940
 3950 3960 3970 3980 3990 4000 4010 4020 4030 4040 4050 4060 4070 4080 4090 4100 4110 4120 4130 4140
 4150 4160 4170 4180 4190 4200 4210 4220 4230 4240 4250 4260 4270 4280 4290 4300 4310 4320 4330 4340
 4350 4360 4370 4380 4390 4400 4410 4420 4430 4440 4450 4460 4470 4480 4490 4500 4510 4520 4530 4540
 4550 4560 4570 4580 4590 4600 4610 4620 4630 4640 4650 4660 4670 4680 4690 4700 4710 4720 4730 4740
 4750 4760 4770 4780 4790 4800 4810 4820 4830 4840 4850 4860 4870 4880 4890 4900 4910 4920 4930 4940
 4950 4960 4970 4980 4990 5000 5010 5020 5030 5040 5050 5060 5070 5080 5090 5100 5110 5120 5130 5140
 5150 5160 5170 5180 5190 5200 5210 5220 5230 5240 5250 5260 5270 5280 5290 5300 5310 5320 5330 5340
 5350 5360 5370 5380 5390 5400 5410 5420 5430 5440 5450 5460 5470 5480 5490 5500 5510 5520 5530 5540
 5550 5560 5570 5580 5590 5600 5610 5620 5630 5640 5650 5660 5670 5680 5690 5700 5710 5720 5730 5740
 5750 5760 5770 5780 5790 5800 5810 5820 5830 5840 5850 5860 5870 5880 5890 5900 5910 5920 5930 5940
 5950 5960 5970 5980 5990 6000 6010 6020 6030 6040 6050 6060 6070 6080 6090 6100 6110 6120 6130 6140
 6150 6160 6170 6180 6190 6200 6210 6220 6230 6240 6250 6260 6270 6280 6290 6300 6310 6320 6330 6340
 6350 6360 6370 6380 6390 6400 6410 6420 6430 6440 6450 6460 6470 6480 6490 6500 6510 6520 6530 6540
 6550 6560 6570 6580 6590 6600 6610 6620 6630 6640 6650 6660 6670 6680 6690 6700 6710 6720 6730 6740
 6750 6760 6770 6780 6790 6800 6810 6820 6830 6840 6850 6860 6870 6880 6890 6900 6910 6920 6930 6940
 6950 6960 6970 6980 6990 7000 7010 7020 7030 7040 7050 7060 7070 7080 7090 7100 7110 7120 7130 7140
 7150 7160 7170 7180 7190 7200 7210 7220 7230 7240 7250 7260 7270 7280 7290 7300 7310 7320 7330 7340
 7350 7360 7370 7380 7390 7400 7410 7420 7430 7440 7450 7460 7470 7480 7490 7500 7510 7520 7530 7540
 7550 7560 7570 7580 7590 7600 7610 7620 7630 7640 7650 7660 7670 7680 7690 7700 7710 7720 7730 7740
 7750 7760 7770 7780 7790 7800 7810 7820 7830 7840 7850 7860 7870 7880 7890 7900 7910 7920 793

ESTIMATED QUANTITIES

1944	1	24" CM	Aluma. 1934 w/curb
1944	1	72"x72" diaphragm	1949.
2	ea.	36"x36" Baffle	
5	ea.	24"x24" Waterfight Bands	
1	ea.	Standard Prop.	
4627	(4131)		
8996			
795	cy.	Gate Trench (Estimated)	

C. H. Hulse, Tommy
 C. H. Hulse, Tommy
 C. H. Hulse, Tommy

ANALYSIS OF THE ECONOMIC

U.S. DEPARTMENT OF AGRICULTURE
Soil Conservation Service

Rice	12-67	John F. Rice
M. 1201	12-67	Area Engineer

APPENDIX D
HYDRAULIC AND HYDROLOGIC DATA

HYDROLOGIC COMPUTATIONS

1. The SCS dimensionless unit hydrograph and the systemized computer program HEC-1 (Dam Safety Version), July 1978, prepared by the Hydrologic Engineering Center, U.S. Corps of Engineers, Davis, California, were used to develop the inflow hydrographs (See this Appendix).
 - a. Twenty-four hour, one percent probabilistic rainfall for the dam location was taken from the data for the rainfall station at Kirksville, MO. as supplied by the St. Louis District, Corps of Engineers per their letter dated 4 March 1980. The twenty-four hour probable maximum precipitation was taken from the curves of Hydrometeorological Report No. 33 and current Corps of Engineers and St. Louis policy and guidance for hydraulics and hydrology.
 - b. Drainage area = 0.478 square miles (306 acres).
 - c. Time of concentration of runoff = 32 minutes (computed from the "Kirpich" formula. This compares to 32 minutes based on Calif. Hwys & P.W. formula).
 - d. The antecedent storm conditions for the probable maximum precipitation were heavy rainfall and low temperatures which occurred on the previous 5 days (SCS AMC III). The antecedent storm conditions for the one percent probabilistic precipitation were an average of the conditions which have preceded the occurrence of the maximum annual flood on numerous watersheds (SCS AMC II). The initial pool elevation was assumed at the invert of the principal spillway.
 - e. The total twenty-four hour storm duration losses for the one percent probabilistic storm were 1.52 inches. The total losses for the PMF storm were 0.62 inches. These data are based on SCS runoff curve No. 87 (SCS Plans) and No. 95 for antecedent moisture conditions SCS AMC II and AMC III respectively. The watershed is composed entirely of SCS soil group D (Leonard-Mexico-Putnam Soil Association). Land use is equally divided between the usual farm cultivated crops, grassland, and farmstead areas.
 - f. Average soil loss rates = 0.03 inch per hour approximately (For PMF storm, AMC III).
2. The combined discharge rating consisted of three components: the flow through the principal spillway, the flow through the emergency spillway and the flow going over the top of the dam.
 - a. The principal spillway rating was developed by using the methods and formulas found in SCS TR No. 3, "Hood Inlets for Culvert Spillways".


- b. The emergency spillway rating curve was developed using the Corps of Engineers, Water Surface Profile HEC-2 computer program. The slope-area method was used assuming an estimated energy slope of 0.016 ft/ft.
 - c. The flows over the dam were determined by using the dam overtopping analyses (irregular top of dam) within the HEC-1 (Dam Safety Version) program.
3. Floods were routed through the reservoir using the HEC-1 (Dam Safety Version) program to determine the capabilities of the spillway and dam embankment crest. The input, output and plotted hydrographs are attached in this Appendix.


SYNOPSIS **THEME** **CHARACTERS**

Illustrate New Verb: *Produce* (15, 2)

GRAPH PAPER









[illegible]

RUN DATE 01/01/20.
TIME 15.35.51.

NO	NIR	NMIN	IDAY	JHR	JMIN	METRIC	IPLT	IPRT	NSTAN
288	0	5	0	0	0	0	0	3	0
			JOPER	NWT	LROPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED

HYIOS=	.05	.10	.15	.20	.25	.35	.50	1.00
NPLAN=1 NRTIO=8 CRTIO=1								

.....

.....

.....

.....

.....

SUB-AREA RUNOFF COMPUTATION

CALCULATION OF INFLO HYDRO TO UPPER RESERVOIR

ISTAQ	ICOMP	LECON	ITAPE	JPLT	JPRY	INAME	ISTAGE	IAUTO
000001	0	0	0	0	0	1	0	0

HYDROG	1	TAKEA	0.00	SNAP	0.00	TRSDA	0.42	HYDROGRAPH DATA	RATIO	ISNOW	ISAME	LOCAL
	2	.48	0.00						0.000	0	1	0

	R6	R72	R96
PMS	102.00	130.00	0.00
SPFE	24.20	0.00	0.00
PRECIP DATA			
	H12	H48	H96
	121.00	0.00	0.00

LOSS DATA									
ALHPT	STAKK	ULTKR	RTIOL	ENAIN	RTIOK	STRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	1.00	-1.00	-95.00	0.00	0.00

CURVE NO = -95.00 WEINSS = -1.00 EFFECT CN = 95.00

UNIT HYDROGRAPH DATA
IC= 0.00 LAG= .32

```
SYRIQ= 0.00 RESESSION DATA RTION= 1.00
ORCSN= -.01
```

UNIT HYDROGRAPH	21	END OF PERIOD	COORDINATES,	TC=	0.00	HOURS,	LAGE=	.32	VOL=	1.00	109.
84:	260.	528.	640.	504.		341.	227.		158.		
74:	50.	34.	16.	11.		8.	6.		4.		12.

[illegible]

.....
.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

.....
.....

STATION 000002, PLAN 1, RATIO 7 1/2 PMF
END-OF-PERIOD HYDROGRAPH ORDINATES


STORAGE


[illegible]

400.	INFLW(I); OUFLOW(O) AND OUSRVLD FLOW(I)
600.	1200. 1600. 2000. 2400.

• JAO •


PLATE D-15







STATION000002

UVF







PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS							
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8
				.05	.10	.15	.20	.25	.35	.50	1.00
HYDROGRAPH AT	000001	1.24	1	202	418	627	836	1045	1464	2091	4182
				5.92	11.84	17.76	23.69	29.61	41.45	59.21	118.43
ROUTED TO	000002	1.24	1	.24	.53	.81	1.09	1.37	1.86	2.41	3.87
				1.50	1.50	4.38	11.09	20.07	33.59	51.01	108.86

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 97.00 115. 110.	SPILLWAY CREST 97.00 115. 110.	TOP OF DAM 100.20 194. 136.	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS			
.05	98.26	0.00	159.	4.	0.00	18.67	0.00
.10	99.59	0.00	167.	53.	0.00	18.31	0.00
.15	100.29	.07	167.	155.	2.00	17.23	0.00
.20	100.94	.94	204.	392.	3.04	17.33	0.00
.25	101.22	.74	236.	709.	3.67	16.17	0.00
.30	101.49	1.02	235.	1166.	4.92	16.00	0.00
.35	101.73	1.29	234.	1602.	6.25	16.00	0.00
.40	102.13	1.33	255.	3037.	9.33	16.00	0.00
1.00							